

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
fee	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator TEXAS CRUDE, INC.		8. Farm or Lease Name Tomlinson	
3. Address of Operator 508 Wall Towers East, Midland, Texas 79701		9. Well No. One	
4. Location of Well UNIT LETTER M 330 FEET FROM THE West LINE AND 330 FEET FROM THE South LINE, SECTION One TOWNSHIP 18S RANGE 38E NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 3661 GR.		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Squeezed off perforations 5198-5261 to 3000# with 150sx. cm. on 6-21-73. Drilled out cm. to top of float collar, tested casing to 1000#, held OK. Drilled float collar and cm. to 5319'. Drilled formation to 5323. Cored from 5323 to 5380, set Lynes formation pkr. at 5355. Acidized 5360-5380 with 500 gals. , 15% acid on 7-7-73. Tested water. Now preparing to plug and abandon.
Will set Bridge plug at 5140' with 2 sx. cm. on top. Circulate hole with 9# mud on 7-11-73. Lea County Casing Pullers will finish plugging well starting on 7-17-73.
Plugging Procedure: Place 35 sx. plug top of 4 1/2" stub, 50 sx. plug bottom of 8 5/8" casing at 369', 10sx. plug top of 8 5/8" and weld steel plate on top of 8 5/8" casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. N. Little

TITLE Dist. Supt.

DATE 7-10-73

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: