

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4735	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry		7. Unit Agreement Name
2. Name of Operator John H. Hill		8. Farm or Lease Name Shell State
3. Address of Operator 1411 West Avenue, Suite 100, Austin, Texas 78701		9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>18S</u> RANGE <u>34E</u> N.M.P.M.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4037 G.L., 4046 K.B.		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Started plugging 9-17-73. Pumped 25 sk. cement plug down casing, spotted top @ 3081'. Cut 4-1/2" casing @ 2,680', spotted 35 sk. cement plug at stub. Pulled casing to 2002', spotted 40 sk cement plug. Pulled casing to 503', spotted 50 sk. cement plug, left mud between plugs. Set 10 sk cement plug at surface, set dry hole marker. Plugged and abandoned 9-18-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Nathan E. Clegg</u>	TITLE <u>Superintendent</u>	DATE <u>9-20-73</u>
APPROVED BY <u>Nathan E. Clegg</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		