

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
K-5001	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		7. Unit Agreement Name
2. Name of Operator Union Oil Company of California		8. Farm or Lease Name Pipeline State Com-
3. Address of Operator P. O. Box 671 Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1880</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat E-K Bone Springs
11. Elevation (Show whether DF, RT, GR, etc.) 3959.5' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-16-83 - MIRUPU. Hot watered tbg.
- 11-17-83 - POOH w/rods, pump & tbg. Set CIBP @ 9450'.
- 11-19-83 - Ran tbg O'ed to 9450'. Disp hole w/mud - sptd 10sx cmt 9450-9350'. PLUG NO. 1
- 11-22-83 - Ran 4-1/2" jet cutter & cut 5-1/2" csg @7502'. POOH w/224 jts (7470')
5-1/2" csg.
- 11-29-83 - Spot 50 sx Cl "C" cmt on top of 5-1/2" csg stub from 7502-7302'. PLUG NO. 2
PU to 5351' & spot 50 sx Cl "C" cmt across 8-5/8" csg shoe from 5351-5158'.
PLUG NO. 3
- 11-30-83 - PU & spot 40 sx Cl "C" cmt inside 8-5/8" csg from 595-440'. PLUG NO. 4
PU & circ 25 sx Cl "C" cmt from 125' to surface. PLUG NO. 5
- 12-01-83 - Cut off well head, weld on P&A plate & install 4" x 4' dry hole marker.
WELL P&A 12-01-83.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.R. Hughes TITLE Dist Drlg Supt. DATE 12-28-83

APPROVED BY Ronald M. [Signature] TITLE OIL & GAS INSPECTOR DATE APR 3 1984

CONDITIONS OF APPROVAL, IF ANY: