

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240

SUBMIT IN TRIPPLICATE  
(Other instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-63026
2. NAME OF OPERATOR MURPHY OPERATING CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Drawer 2648, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 660' FWL (Unit Ltr. D)		8. FARM OR LEASE NAME West 7 Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DY, RT, GR, etc.) 3665.3' G.R.		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 7, T-19S, R-33E
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-3-85 RU PU.

12-4-85 Unseated pump & TIH & TOH w/rods & layed dn. pump. Nippled dn WH, changed elev. & unseated pkr. RTTS, let fluid equalize. Layed dn. 3 jts. of 2-7/8" tbg. TOH for CIBP & perf. RU loggers & TIH w/CIBP & set CIBP @ 3960' & dumped 10' cmt. on top. TIH w/perf. guns & perf. as follows: 3759'-3766' @ 1 J.S.P.F. for a total of 8 holes. RD loggers & TIH w/2-7/8" tbg. to 3770' & spotted w/2 bbls. 15% MCA acid. Layed dn. 3 jts. 2-7/8" tbg. & set RTTS pkr. @ 3684.51'. Broke dn. perms. & swabbed tbg. dry. Completed acid job as follows: Well broke dn. @ 3700# psi; 666 gals. 15% MCA acid; 16 ball sealers (well balled off); Max. press. @ 4300# psi. - Avg. press @ 2534# psi; Max. rate = 4.1 BPM - Avg. rate - 3.5 BPM; flushed w/2% KCl - 23 bbls.; Total bbls. to rec. - 40 bbls.; ISIP 2450# psi, 5 min, 1540# psi, 10 min 1100# psi.; 15 min. well flowed dn. RU lubricator & made 4 swabb runs to S.N. Rec. 24 bbls. - 16 bbls. left to rec. SDFN.

12-5-85 SITP @ 50# psi. for 13.5 hrs. Opened 1" bleed line dn. 1" hose. Tried to burn, no show of gas. RU lubricator & started swabbing @ 7:30 a.m. Tank

CONTINUED ON PAGE 2

I hereby certify that the foregoing is true and correct

SIGNED Lois N. Brown TITLE Production Clerk DATE December 9, 1985

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

DEC 11 1985

\*See Instructions on Reverse Side



MURPHY OPERATING CORPORATION

ROSWELL PETROLEUM BUILDING

ROSWELL, NEW MEXICO 88201

MAN FOR  
P. 21  
TEL. E  
505 10

BLM FORM 3160-5 - SUNDRY NOTICES AND REPORTS ON WELLS dated December 9, 1985, Page 2

TONTO WEST 7 FEDERAL #1  
Wildcat (Queen - Penrose Test) RE-ENTRY  
Federal Lease No. NM-63026

660' FNL & 660' FWL, (Unit Ltr. D) W1/2 Section 7, T-19S, R-33E,  
Lea County, New Mexico

12-5-85 CONTINUED -

gauged @ 12". Gauged tank @ 9:30 a.m. - 18" = 44 bbls. Rec. - 4 bbls. overload. Swabbing back 7 bbls./hr. Made 7 more runs w/F.L. @ 3300'. Gauged tank - 19" = 47 bbls. Rec. - 7 bbls. overload. No show of oil or gas. Made 7 more runs - F.L. @ 3300'. Gauged tank @ 12:00 P.M. noon - 20" - 51 bbls. Rec. - 11 bbls. overload. Layed dn. lubricator & swabbed line. RU rod elev. & TIH w/rods as follows:

2" X 1-1/2" X 12' RWTC pump  
2' X 3/4" rod sub, top of pump  
145 X 3/4" rods  
22' X 1-1/4" polish rod, w/10' X 1-1/2" liner

Started motor, left running w/good pump action (NOTE: 28 jts. 2-7/8" tbg. on ground & 20 3/4" rods). TOH & RD.

RECEIVED  
JAN 30 1987  
OCD  
HOBBS OFFICE