· · · · · · · · · · · · · · · · · · ·	
NO. C? COPIES RECEIVED	
The state of the s	Form C-103
DISTRIBUTION	Supersedes Old C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State X Fee
OPERATOR	5. State Oil & Gas Lease No.
	K-5190
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOI 1.	1R. ()
OIL GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Read & Stevens, Inc.	State "EK"
3. Address of Operator	9, Well No.
P. O. Box 2126, Roswell, New Mexico 88201	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER M . 330 FEET FROM THE SOUTH LINE AND 990	
FEET FROM THE DOUGHT LINE AND 990	Undesignated
THE West LINE, SECTION 5 TOWNSHIP 18S RANGE 34E	
TOWNSHIP TO RANGE JED	нмрм. ///////////////////////////////////
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4069.3 GR	Lea
Check Appropriate Box To Indicate Nature of Notice, Repo	
SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOE OTHER	SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQE	SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOE OTHER	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOE OTHER	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOE OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703.	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged Well in following manner:	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged well in following manner:	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged Well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'.	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged Well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'.	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1 fos. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'.	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'	ALTERING CASING PLUG AND ABANDONMENT
PLUG AND ABANDON PULL OR ALTER CASING TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged Well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.	ALTERING CASING PLUG AND ABANDONMENT including estimated date of starting any proposed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.	ALTERING CASING PLUG AND ABANDONMENT including estimated date of starting any proposed
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.	ALTERING CASING PLUG AND ABANDONMENT including estimated date of starting any proposed
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.	ALTERING CASING PLUG AND ABANDONMENT including estimated date of starting any proposed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1703. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.	ALTERING CASING PLUG AND ABANDONMENT including estimated date of starting any proposed
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged well in following manner: 1. Hole full of good mud 10.2 wt., 40 Vis. 2. Set 35 sx. cement plug 4226'-4126'. Set 35 sx. cement plug 2960'-2860'. Set 35 sx. cement plug 1925'-1825'. Set 35 sx. cement plug 370'- 270'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.	ALTERING CASING PLUG AND ABANDONMENT including estimated date of starting any proposed

APPROVED BY ALLE OF APPROVAL, IF ANY:

TITLE Agent

DATE APPRIL 9, 1974