

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24731
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2516
7. Lease Name or Unit Agreement Name Devon State
8. Well No. 1
9. Pool name or Wildcat Maljamar, Penn Leamy

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook St., Odessa, Texas 79762	
4. Well Location Unit Letter I : 1874 Feet From The South Line and 554 Feet From The East Line Section 22 Township 17-S Range 33-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4139.9 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Squeeze casing leak ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-13-90: Rigged up. GIH w/RBP & pkr on 2-3/8" tbq. Set RBP @ 6000'. GIH w/cmt retainer on 2-3/8" tbq.

2-23-90: Set cmt retainer @ 4910'. Pmp 200 sx prem plus Class C cmt containing 4% gel & 2% CaCl (wtb 5 ppg). Pump 100 sx prem plus Class C cmt w/2% CaCl (wt 14.8 ppg). Displace w/FW to leave 6 bbls cmt in tbq. Close bradenhead valve & hesitate squeeze to 1500#. Pull out of retainer. Circ. hole clean. WOC until 2-26-90.

2-26-90: GIH w/ 4-3/4" bit, 4 X 3-1/2" DC & 2-3/8" tbq to 4905'. Drill out cmt on retainer & drill retainer.

3-1-90: Drill out cmt to 5233'. Test csg to 650# - OK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. L. Maples TITLE Assist., Reg. & Pro. DATE 6/25/90

TYPE OR PRINT NAME J. L. Maples

TELEPHONE NO. 367-1411

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 10 1990

3-2-90: GIH w/2-3/8" tbg to 11200'. Remove BOP. NU wellhead.
3-5-90: Rig down.
3-8-90: Temporary drop.
4-30-90: MI RU Diamond WS. Install BOP.
5-1-90: GIH w/mud anchor, SN, 10 jts tbg, TAC & 2-3/8" tbg to 11200'.
Start in hole w/2 X 1-1/16" X 22' pmp.
5-8-90: Pmpd 24 hrs. Rec 52 BW. Temporary drop.

JUL 8 1990

HOBBES ON