

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
STATE		
FED.		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-605	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
CleveRock Energy Corporation		CleveRock-Pedco State	
3. Address of Operator		9. Well No.	
9720-B Candelaria NE, Albuquerque, New Mexico 87112		1	
4. Location of Well		10. Field and Pool, or Willcut	
UNIT LETTER I, 660 FEET FROM THE East LINE AND 2030 FEET FROM		East Lusk	
THE South LINE, SECTION 16 TOWNSHIP 19S RANGE 32E NMPM.			
15. Elevation (Show whether DE, RT, GR, etc.)		12. County	
3617 GL		Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Perforate with radial jet 9918 feet
2. Set packer at 9910 feet. Attempt to break down perforations at 9918 feet.
3. Set packer at 9500 feet, squeeze perforations 9884-9896 and 9918 feet with 100 sacks, wash out cement, WOC 4 hours, pressure test, resqueeze if necessary.
4. Perforate 9899-9908 feet with 2 JHPF.
5. Swab test and acidize as warranted.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	Agent	DATE	8/29/75
APPROVED BY		TITLE	
Geologist		SEP 2 1975	
CONDITIONS OF APPROVAL, IF ANY:			