

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

NE
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-6863

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Anadarko Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Querecho Plains Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

27: 18-32

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER **DRY**

2. NAME OF OPERATOR

BURLESON and HUFF

3. ADDRESS OF OPERATOR

P.O.Box 935-Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**1650' from South line and
2310' from East line**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3723 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request approval for following procedure to plug and abandon well:

255X 100' cement plug @ 3040' - 2940' above tested Yates-Seven Rivers perforations
255X 100' plug @ base of salt (2540') 2500 - 2950
255X Cut & pull 4 1/2" pipe and place 100' plug in and out of stub
255X 100' plug @ top of salt (1235') 1150 - 1250
255X 100' plug at base of surface pipe (330') 240 - 340
10' plug in top of surface pipe with appropriate marker
Mud will be placed in hole between plugs
Surface will be put back to original contour

**You will be notified in sufficient time to be present at well site
when this work is performed**

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Partner

DATE

June 12, 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED
AS AMENDED
JUN 26 1975
ARTHUR R. BRUSH
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.