

COPY TO O. C. C.
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE.
(Other instructions reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-4609

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Anadarko "A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Querecho Plains Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28, T18S, R32E

12. COUNTY OR PARISH 13. STATE

Lea

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒

Dry

2. NAME OF OPERATOR

Burleson & Huff

3. ADDRESS OF OPERATOR

P. O. Box 935, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface330' from the East and 1650' from the South lines of
Section 28

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3721 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This well was plugged in the following manner and was supervised by your field man:

25 sx plug @ 3615' to 3965'

25 sx plug @ base of salt @ 2550' to 2800'

Cut and pulled 2290.06' of 4½" pipe

35 sx plug in and out of stub @ 2290'

35 sx plug top of salt from 1240' to 1140'

35 sx plug @ base of surface pipe, 334' to 234'.

10 sx plug @ surface with marker

Mud placed in hole between plugs. We are waiting for recommendations concerning final
clean up and requirements so this location can pass inspection for final approval.

P+H 9-16-75

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Co-Owner

DATE 10-6-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

FEB 20 1979

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side