

DISTRICT I

1625 N. French Drive, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-25020
2. Name of Operator OCCIDENTAL PERMIAN, LTD.	5. Indicate Type of Lease FED <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 1017 W STANOLIND RD.	6. State Oil & Gas Lease No.
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>14</u> Township <u>18-S</u> Range <u>37-E</u> NMPM LEA County	7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT SECTION 14
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3678' GL	8. Well No. 441
	9. Pool name or Wildcat HOBBS (G/SA)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify the NMOCD prior to job. (393-6161)

RUPU. Move in and rack workstring.
RIH w/4.5" csg scraper to 4000'.
RIH w/4.5" CIPB and set @3980'.
Top perf @4030'.
Cier csg w/pkr fluid.
Test csg to 500 psi for 30 min and chart for the NMOCD.
RDPU. Clean Location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Gilbert TITLE Completions Specialist DATE 11/24/2001
TYPE OR PRINT NAME R.N. GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE NOV 27 2001
CONDITIONS OF APPROVAL IF ANY: