

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-025-25121

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-3936-1

7. Lease Name or Unit Agreement Name:

New Mexico AA State NCT-4

8. Well No.

4

9. Pool name or Wildcat

Vacum ABO REEF

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator

Chevron USA, Inc.

3. Address of Operator

15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter A : 919 feet from the north line and 401 feet from the east line

Section 10

Township 18-S

Range 34-E

NMPM

County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24hrs prior to MI & RU
2. Set 5 1/2 CIBP @ 5000, spot 25sx plug 5000-4800(San Andres) WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL.
4. Spot 25sx plug 4100-3900(Queen)
5. Spot 25sx plug 3000-2800(B-salt) WOC Tag.
6. Spot 25sx plug 1875-1675(8 5/8 shoe, T-salt) WOC Tag.
7. Spot 30sx plug 300-surf(surf) WOC Tag.
8. Install dry hole marker.

THIS DOCUMENT IS THE PROPERTY OF THE STATE OF NEW MEXICO. IT IS TO BE KEPT IN THE OFFICE OF THE FIELD REPRESENTATIVE II/STAFF MANAGER. IT IS TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

D.R. Buehner

TITLE

HES Specialist

DATE

12/19/2002

Type or print name

(This space for State use)

Telephone No.

APPROVED BY

GARY W. LARK

DATE

Conditions of approval, if any:

GARY W. LARK
OCD FIELD REPRESENTATIVE II/STAFF MANAGER

PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR CHEVRON USA INC.

LEASE NAME NEW MEXICO "AA" STATE NCT-4


WELL # 4

SECT 10 TWN 18-S RNG 34-E

FROM 919 NSL 401 EWL

TD 9050 FORMATION @ TD ABO

PBTD FORMATION @ PBTD SAN ANDRES



TD 9050

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	8 5/8	1823	SURF	CIRC
INTMED 1				
INTMED 2				
PROD	5 1/2	9050	2400	T.S

	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					

	CUT & PULL	TOP - BOTTOM
INTMED 1		PERFS
INTMED 2		OPENHOLE
PROD		

*REQUIRED PLUGS DISTRICT

	PLUG	TYPE PLUG	SACKS CEMENT	DEPTH
RUSTLER (ANHYD)	1	CIBP	25	5000
YATES	2	QUEEN	25	4100
QUEEN	3	B-SALT	25	3000
GRAYBURG	4	8 5/8 S	25	1875
SAN ANDRES	5	SURF	30	300
CAPITAN REEF				
DELAWARE				
BELL CANYON				
CHERRY CANYON				
BRUSHY CANYON				
BONE SPRING				
GLORIETA				
BLINBRY				
TUBB				
DRINKARD				
ABO				
WC				
PENN				
STRAWN				
ATOKA				
MORROW				
MISS				
DEVONIAN				