

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25207
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2244
7. Lease Name or Unit Agreement Name North Vacuum Abo North Unit 14
8. Well No. #3
9. Pool name or Wildcat Vacuum Abo North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Sage Energy Company	
3. Address of Operator P.O. Drawer 3068 Midland, Texas 79702	
4. Well Location Unit Letter E : 2180 Feet From The North Line and 660 Feet From The West Line Section 12 Township 17-S Range 34-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4030.1 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Requesting TA'D Status <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-25-97 RIH with Howco CIBP on tubing, set at 8483' KB, POH with one joint to 8461' KB, circulate hole with 2% KCL water and packer fluid, POH and laid down tubing. Well TA'D. Test BP to 500 psi for 30 minutes and chart.

Chart attached.

This Approval of Temporary
Abandonment Expires 2-6-2002

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tonya Streun TITLE Production Clerk DATE 3-4-97
TYPE OR PRINT NAME Tonya Streun (915) 683-5271
TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAR 06 1997

JCS

do

TUESDAY

NOON

PM

THURSDAY

PM MIDNIGHT 1 AM

FRIDAY

NOON

PM

AM

SATURDAY

AM

PM

MONDAY

CLARK 14 #3
1-25-97

Sage Energy Co

Winters by
State 3 (10/17)
Sage Energy Co
LARRY LOPP