

**COPY TO O. C. C.**  
**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**GEOLOGICAL SURVEY**

SUBMIT IN TRIPPLICATE  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 062903

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hightower

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Watkins-Grayburg

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

31-18-32

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

E. B. Clark Sr.

3. ADDRESS OF OPERATOR

700 City National Bank Bldg., Wichita Falls, Texas 76301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

1650 FSL & 1980 FWL of Sec. 31, T18S, R32E.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3668 G.L.

16.

**Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged and abandoned well by balance plug method (4 plugs - 85 sks. Halliburton Class "H") as follows:

(1) Mixed 100 bbls. bentonite gel mud & circulated hole w/mud

(2) Set 25 sx plug from 4247' to 3917'

(3) Set 25 sx plug from 2687' to 2357'

(4) Set 25 sx plug from 1119' to 789"

(5) Set 10 sx plug from 126' to surface

(6) Removed surface equipment - job complete 12 Noon 4/18/79. Well was plugged as swab test indicated 100% S.W. & no other indications of Hydrocarbons were found.

**RECEIVED**

**APR 23 1979**

**U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer (Agent)

DATE

4-19-79

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED**

**AUG 13 1979**

**ACTING DISTRICT ENGINEER**

\*See Instructions on Reverse Side

RECEIVED

AUG 14 1979

O.C.D. HOBBS, OFFICE