

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

DE*
re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR MEWBOURNE OIL COMPANY		8. FARM OR LEASE NAME ANADARKO FED
3. ADDRESS OF OPERATOR P.O. BOX 5270 - HOBBS, NEW MEXICO 88241		9. WELL NO. 6
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990/2 + 1652/10		10. FIELD AND POOL, OR WILDCAT Guadalupe Plains Guadalupe
14. PERMIT NO. 30-025-25260		11. SEC., T., R., M., OR B&M. AND SURVEY OR ASMA SOC 27 T-18-S R-32E UNIT LETTER N 990 FSL 1650 FWL
15. ELEVATIONS (Show whether DP, RT, GR, etc.)		12. COUNTY OR PARISH LEA
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. SET 4½ CIBP AT 3850'
2. SPOT 10 SKS CEMENT ON TOP OF 4½ CIBP
3. LOAD HOLE W/MUD
4. CUT O PULL 4½ CASING FROM 2344'
5. SPOT 25 SKS CEMENT AT 3025' O ACCROSE FIRST CASING SHOT
6. SPOT 25 SKS CEMENT AT 2400' O WOC AT 4½ STUB TAGGED AT 2275'
7. SPOT 30 SKS CEMENT AT 1305' O WOC TAGGED AT 1220'
8. SPOT 45 SKS CEMENT AT 420' WOC TAGGED AT 385'
9. SPOT 30 SKS CEMENT AT 385' CALCULATED TOP CEMENT AT 305'
10. SPOT 20 SKS CEMENT AT 64' TO SURFACE AND SET UP P&A MARKER.

18. I hereby certify that the foregoing is true and correct

SIGNED Raymond Maldonado

TITLE P&A SUPERVISOR

DATE 7-25-91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side