

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-069276

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Indian
tribe name

7. UNIT AGREEMENT NAME

UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hudson-Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T18S, R33E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Robert N. Enfield

3. ADDRESS OF OPERATOR

P. O. Box 2431, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FNL & 1980 FWL, Sec. 30, T-18-S, R-33-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3784.4

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Load hole with 9.8# mud.
Prep to set cement plugs
Plug #1 @ 12700' - 12800' w/50 sx.
Plug #2 @ 11900' - 12000'
Plug #3 @ 10200 - 10300'
Plug #4 @ 7000' - 7100'
Plug #5 @ 5200 - 5400' s/75 sx.
Plug #6 @ 4970 w/65 sx.
Plug #7 @ 2931 w/50 sx.
Plug #8 @ 1328' w/50 sx Class H.
Set surface plug
Plugs completed 10/25/76
Install regulation marker
Clean location, when pits dry

As per verbal approval

In addition to normal filling of pits
and cleanup of location, well pad and
access road should be ripped in accordance
with attached "Ripping Recommendations"
(3109).

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert N. Enfield

TITLE Operator

DATE 11/9/76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

NOV 12 1976
ARTHUR R. BROWN
DISTRICT ENGINEER

DATE

*See Instructions on Reverse Side