- Restoration of Surface: If well is productive, pits will be backfilled and 10. leveled as soon as practical. The plastic pit liner will be placed in the bottom of the pit before backfilling. Upon final abandonment the well site will be leveled and cleaned and the road ripped, with land returned as near as practical to original condition.
- Operator's Representatives: Field personnel who can be contacted concerning 11. compliance of this Surface Use Plan are as follows:

Drilling and Production: James F. O'Briant

306 Bldg. of the Southwest

Midland, Texas 79701

Office Phone - (915) 683-5511 Home Phone - (915) 692-8907

OR

Robert N. Enfield P. O. Box 2431

Santa Fe, New Mexico 87501

Office Phone - (505) 988-2863 Home Phone - (505) 982-0092

Certification: 12.

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by Robert N. Enfield and its contractors and sub-contractors in conformity with this plan and the terms and conditions under which it is approved.

June 16, 1976

Name and Title

Robert N. Enfield, Operator

## RECEIVED

JUL 13 1976

Conservation comm.