

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Authority: 1004-0-0-0
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-14903

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Corbin Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

South Corbin Wolfcamp

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 20, T18S, R33E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" (Form 3160-1) for such purposes.)

HOBBBS, NEW MEXICO 88240

1. OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER ☐
2. NAME OF OPERATOR
C. W. Trainer
3. ADDRESS OF OPERATOR
c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, NM 88241
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below)
At surface 660' FSL & 1980' FWL of Sec. 20

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3799.7 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work began 9/5/83. Treat perfs 11124-164 with 1500 gallons 15% HCL acid. Swab dry. Set CIPB at 11100, perf 10826-836 & 10,936-962 & treat with 2,000 gallons acid. Swab water. Set ret BP, swab 100% water from perfs 10,936-962, swab 10% oil from perfs 10,826-836. Set retainer at 10912 & squeeze perfs 10,936-962 with 150 sacks. Found PBTD at 10909. Ran rods & pump. Pumped water. Well shut in.

Work began 9/28/85. Perf 10948-958 with 4 shots per foot, treat with 4,000 gallons 15% acid. Swab water, no shows.

It is now planned to perf Bone Springs at approximately 9025 and test for possible production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Wanna Haller

TITLE Agent

DATE

10/24/85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

OCT 30 1985

RECEIVED

OCT 31 1985

NOV 13 1985