

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPL  
(Other instructions  
reverse side)

FE\*  
re-

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
NM 25458

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
--

7. UNIT AGREEMENT NAME  
--

8. FARM OR LEASE NAME

Gulf McKay Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

North Lusk-Morrow

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 34, T18S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
Petroleum Development Corporation

3. ADDRESS OF OPERATOR  
9720 B Candelaria NE, Albuquerque, NM 87112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

660' FSL & 1980' FWL

14. PERMIT NO.

--

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3715 KB

3697 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Recompletion/Workover

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Set Baker CIBP @ 12484; dumped 35' cement on plug; perforated  
Atoka: 12051-12073 with 4 JSPF. Swabbed 15 bbls. salt water per hour.  
Set retainer @ 11998; squeezed with 100 sx. cement @ 4000 psi max.  
Left 35' cement on top of retainer. Perforated Strawn: 11677-11700 with  
4 JSPF. Swabbed salt water and-show of oil. Acidized with 1500 gallons  
15% NE with 1000 c.f. nitrogen per barrel @ 8000 psi, max. Swabbed  
500 barrels salt water in 5 days; no oil.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Secretary

DATE 6/7/78

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

\*See Instructions on Reverse Side

