

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other Instruct
verse side)CATE*
OR re-Form approved.
Budget Bureau No. 42 R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 12413 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sun McKay Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10, T19S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

PETROLEUM DEVELOPMENT CORPORATION

3. ADDRESS OF OPERATOR

9720 B Candelaria NE, Albuquerque, NM 87112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1730' FWL, 1850' FNL,

14. PERMIT NO.

--

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3658 G.L.

3676 K. B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☒
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


1. Set Guiberson Uni-Six packer at 12,615' with positive plug in flow nipple to temporarily abandon the Morrow formation. Perforations: 12,661 to 12,668; 12,698-707, 12736-746, 12,920-926; 12931-935.

2. Perforate Wolfcamp formation: 10,702-743 with 2 JHPF. Run 2-3/8" tubing and packer. Swab in and test; acidize, if necessary.

RECEIVED
MAY 26 1978
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE Secretary

DATE 5/26/78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED
MAY 30 1978
G. D. F.
ACTING DISTRICT ENGINEER

RECEIVED

JUN 06 1970

COMMUNICATIONS SECTION
U. S. AIR FORCE

APPROVED