

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-967
7. Unit Agreement Name
8. Form or Lease Name Getty 11 State
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Harvey E. Yates Company
3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 18S RANGE 35E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3888' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-20-78 Plugged and abandoned in the following manner:

Set plug #1 @ 4771' with 40 Sx
Set plug #2 @ 3233' with 35 Sx
Set plug #3 @ 1800' with 35 Sx
Set plug #4 @ 341' with 35 Sx
Set plug #5 @ 60' - surface with 10 Sx

Plugs #1 thru #4 100' thick and mud weight 10.3.

Dry hole marker installed on top.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Harder TITLE Engineer DATE 1-30-78
APPROVED BY A. H. Stateman TITLE OIL & GAS INSPECTOR DATE 1-30-78
CONDITIONS OF APPROVAL, IF ANY: