Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DISTRICT

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO. 30-025-25820
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5 Indicate Type of Lease
DISTRICT III	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
	B-1306
SUNDRY NOTICES AND REPORTS ON WELLS	<i>\</i>
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well:  OIL GAS WELL OTHER Water Injection	Central Vacuum Unit
2. Name of Operator	8. Well No.
Texaco Exploration and Production Inc.	107
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	9. Pool name or Wildcat
4. Well Location	Vacuum Grayburg San Andres
i de la companya de	32 Feet From The East Line
	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	V/////////////////////////////////////
(/////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of Notice, Re	eport, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	GOPNS. L. PLUG AND ABANDONMENT L.
PULL OR ALTER CASING  CHANGE PLANS  COMMENCE DRILLING  CASING TEST AND CE	
	MENT JOB
PULL OR ALTER CASING  CASING TEST AND CE  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, included the complete of the c	MENT JOB
PULL OR ALTER CASING  CASING TEST AND CE  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, included work) SEE RULE 1103. 9-3-91 thru 9-7-91	ding estimated date of starting any proposed
PULL OR ALTER CASING  CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr.
PULL OR ALTER CASING  CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from
PULL OR ALTER CASING  CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from
PULL OR ALTER CASING  CASING TEST AND CE  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot
PULL OR ALTER CASING  CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclus work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclus work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL.
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-l inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL.
PULL OR ALTER CASING  CASING TEST AND CE  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL.
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-l inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL.
PULL OR ALTER CASING  CASING TEST AND CE  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection.	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivery) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection.  Prior 49 BWPD @ 860 PSI After 471 BWPD @ 860 PSI	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 1bs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL. d hole w/pkr fluid, set
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclus work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection. Prior 49 BWPD @ 860 PSI After 471 BWPD @ 860 PSI  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIONATURE TIME Engineer's A	onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball, 15 MIN 1050#, TL 393 BBL. d hole w/pkr fluid, set
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection.  Prior 49 BWPD @ 860 PSI After 471 BWPD @ 860 PSI  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE M.C. Duncan	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 1bs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL. d hole w/pkr fluid, set
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivers). SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection.     Prior 49 BWPD @ 860 PSI	ding estimated date of starting any proposed  onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball , 15 MIN 1050#, TL 393 BBL. d hole w/pkr fluid, set  SSISTANT DATE 9-17-91  TELEPHONE NO. 393-7191
CASING TEST AND CE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. 9-3-91 thru 9-7-91  1. MIRU. TOH w/tbg, TIH w/spear on 2.375" workstring, latched 2. TIH w/bit, cleaned out to 4754', spotted 350 gals 4% NA-Pe 4244'-4710'; SI 3 hrs, TOH w/workstring & drill collars.  3. Rigged up wireline; Perf 4 1/2" csg w/2 JSPF @ 4244', 55', 4300', 10', 18', 22'. (11 intervals, 22 holes)  4. TIH w/pkr & spot control valve to 4750', spotted 350 gals. control valve.  5. Acidized perfs from 4244'-4710' w/10000 gal. 15% NEFE, 600 sealers, max TP 3050#, min TP 2000#, AIR 5 BPM, ISIP 1700#  6. TOH laying down workstring, TIH w/AD-1 inj. pkr, circulate pkr @ 4182, tested csg @ 500 PSI- 30 min.  7. Returned well to injection.  Prior 49 BWPD @ 860 PSI After 471 BWPD @ 860 PSI  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE M.C. Duncan	onto pkr @ 4260', TOH w/pkr. rborate (100#) from  65', 74', 83', 89', 93',  15% HCL NEFE, pulled spot  0 lbs rocksalt, 214 ball, 15 MIN 1050#, TL 393 BBL. d hole w/pkr fluid, set

A-CE VAD

SEP 18 1991

CORRES CANCE