

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25821
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1031
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	122
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3970' GR

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	P.O. BOX 730, HOBBS, NM 88240
4. Well Location	Unit Letter <u>O</u> : <u>340</u> Feet From The <u>SOUTH</u> Line and <u>1580</u> Feet From The <u>EAST</u> Line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3970' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: REQUEST TEMPORARY ABANDONMENT STATUS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/25/95 - 3/27/95

- 1) Notified NMOCD 24 hrs prior to proceeding with temporary abandonment procedure.
- 2) MIRU. Installed BOP. Released injection pkr. TOH with injection equipment.
- 3) Cleaned out to 4660'. By wireline, set 4-1/2" CIBP @ 4594'. Capped with 36" cement by bailer. PBTD @ 4558'.
- 4) TIH, tagged cement. Circulated inhibited water. Test casing to 580# for 30 minutes, held ok.
- 5) Sent original chart NMOCD. Request temporary abandonment well status through 3/27/2000.

(Original chart @ NMOCD, copy of chart on back)

(Internal TEF-I status from INJ to ASD-I)

This Approval of Temporary
Abandonment Expires 4-1-2000

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Monte C. Duncan TITLE Engr Asst DATE 4/25/95
TYPE OR PRINT NAME Monte C. Duncan Telephone No. 397-0418

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

DATE MAY 01 1995

