· ·-	
· COPIES =CCCIVED	Form C-103 Supersedes Old C-107 and C-103
NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-55
; FE	Sa. Indicate Type of Lease
FILE	State X Fee
U.S.G.S.	5. State Oil & Gas Lease No.
LAND OFFICE .	L-638
OPERATOR	mmmm
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NU HELD AND KET ON 15 OF TO A DIFFERENT RESERVOIR.  (DO NOT USE THIS FORM FOR PROPOSALS TO ARILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  (DO NOT USE THIS FORM FOR PROPOSALS.)  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
USE "APPLICATION FOR PERSON	/, o.m. //
OIL X WELL OTHER-	8. Farm or Lease Name
Name of Operator	North Scharb State Unit
Mesa Petroleum Co	9. Well No.
3. Address of Operator	1
1000 Vaughn Building/Midland, Texas 79701	10. Field and Pool, or Wildcat
Location of Well 1980 North 660	Wildcat
E 1980 FEET FROM THE NORTH LINE AND OOU FEET FRO	
32 18S 35E	
West 185 RANGE SDE MMPI	MIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3928 GR	Lea ///////
	ther Data
Check Appropriate Box To Indicate Nature of Notice, Report or O	NT REPORT OF:
NOTICE OF INTENTION TO:	
REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUE AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TOWN THE ABANDON	
PULL OR ALTER CASING CASING OTHER	
OTHER	A Long of starting Chy Drop
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including the pertinent of the pertinent dates.)	ng estimated date by starting any pro-
17. Describe Proposed or Completed Operations (Cataly) work) SEE RULE 1103.	
a a zo : Dummad 40! coment on tor	of bridge plug.
	9-5/8" casing at
RII Knox Services & mixed 50 SX cement. Spoots in this fresh water	ar laved II) sack i

RU Welex & set CIBP at 3350' on 8-9-78. Dumped 40' cement on top of bridge plug.
RU Knox Services & mixed 50 sx cement. Spotted 120' of cement in 9-5/8" casing at 1840'-1960'. Pulled 4 stands & reverse circ w/15 bbls fresh water. Layed 10 sack plug at surface. (Brine water 9#/gal between all plugs) Cut off wellhead & installed dry hole marker. Well plugged and abandoned.

Agent

Agent

OIL & GAS INSPECTOR

OATE

CONDITIONS OF APPROVAL, IF ANY:

CONDITIONS OF APPROVAL APPROVAL