

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <u>30-025-25991</u>
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator <u>Anadarko Pet. Corp.</u>		6. State Oil & Gas Lease No. <u>LG-6335</u>
3. Address of Operator <u>PO Drawer 130, Artesia, NM, 88211</u>		7. Lease Name or Unit Agreement Name <u>NM "AH" State</u>
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>West</u> Line and <u>1980</u> Feet From The <u>South</u> Line Section <u>18</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County		8. Well No. <u>1</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3964' GL</u>		9. Pool name or Wildcat <u>Undesignated Wolfcamp</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: <u>Re-entry and P+A</u> ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in drilling rig and installed BOP.
- Drilled out all cement plugs and deepened From 7486 to 10,010'.
- Ran CN/2DL and Dual Induction Laterlog.
- Ran straddle packers for DST #1. (Upper Wolfcamp-9582' to 9627'), Recovered 60 oil and gas cut mud. 120 min shut in pressure = 1822*. TOH.
- Ran straddle packers for DST #2. (Delaware sand - 6556' to 6640'), Recovered 200 bbl water. No oil. 120 min shut in pressure = 2480*. TOH.
- Trip in hole with drill pipe open ended.

Cont.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Braswell TITLE Field Forman DATE 2/21/89

TYPE OR PRINT NAME Mike Braswell TELEPHONE NO. 748-3368

(This space for State Use)

APPROVED BY [Signature] OIL & GAS INSPECTOR

MAY 16 1989

CONDITIONS OF APPROVAL, IF ANY:

R 8W

E

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25991
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-6335
7. Lease Name or Unit Agreement Name NM "AH" State
8. Well No. 1
9. Pool name or Wildcat Undesignated Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3964 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Anadarko Pet. Corp.
3. Address of Operator PO Drawer 130 Artesia, NM, 88211
4. Well Location Unit Letter K : 1980 Feet From The West Line and 1980 Feet From The South Line Section 18 Township 18-S Range 35-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cont.

- Well not productive. Received verbal approval from NMOC to Plug and Abandon. Plugs set as follows: 40 sx, 9547-9667 (across Wolfcamp top); 33 sx, 9293-9393 (across Abu top); 43 sx, 7384-7494 (across Bone Springs top); 47 sx, 5971-6091 (across Delaware top); 35 sx, 3547-3652 (across 8 5/8" casing shoe); 36 sx, 1673-1793 (across Anhy top); 17 sx, 0-50' surface plug.
- Moved off rig and installed P&A marker.

Note: Will cover pits when drilling fluid is dry enough to allow.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Braswell TITLE Field Forman DATE 2/21/89

TYPE OR PRINT NAME Mike Braswell TELEPHONE NO. 748-3368

(This space for State Use)

APPROVED BY [Signature] OIL & GAS INSPECTOR MAY 16 1989
CONDITIONS OF APPROVAL, IF ANY: