

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25998
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857943
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	137
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
205 E. Bender, HOBBS, NM 88240

4. Well Location  
Unit Letter D : 1100 Feet From The NORTH Line and 40 Feet From The WEST Line  
Section 6 Township 18S Range 35E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-5-98: MIRU. NDWH. NUBOP. REL PKR. TIH W/BIT & DC'S ON WS TO 4240'.  
1-6-98: OPEN WELL & BLED DOWN. LOWER TOOLS TO 4282' & TAG W/REV UNIT. BREAK CIRC & C/O 470' FILL TO PBTD 4752'.  
1-7-98: TIH W/PKR SET @ 4248'. PRESS CSG TO 500#-OK. ACIDIZE SAN ANDRES PERFS 4330-4698' W/10,000 GALS 15% NEFE HCL & 6000# RK SLT IN 4 STGS. SWAB & RECVD 50 BLW.  
1-8-98: REL PKR.  
1-9-98: TIH W/PUMP OUT PLUG. REL ON/OFF TOOL. CIRC TRTD WTR. GET BACK ON. NDBOP. NU TREE. TEST PKR & CSG TO 500#-OK. CIW TEST TREE 3000#-OK. PUMP OUT PUMP OUT PLUG. RD.  
1-19-98: ON 24 HR OPT. INJ'G 1963 BWPD @ 1130 PSI. STATUS IS WIW.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/4/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

ORIGINAL SIGNED BY CHRIS WILLIAMS  
(This space for State Use) DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: