

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-12413

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hi-Yo Silver Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 25, T-19-S, R-32-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Cleary Petroleum Corporation

3. ADDRESS OF OPERATOR

P. O. Drawer 2358, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 330' FEL

14. PERMIT NO.

Letter dated 7-14-78

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3579' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. POH w/ 2 3/8" tbg. Set CIBP on wireline @ 2930'. Cap with 35' cement (4½ sx).
2. Weld on 5½" nipple to 5½" csg. Shoot off pipe at lowest free point (approx. 1900') & POH & LD.
3. RIH w/ 2 3/8" tbg. to spot 100' plug half in & half out of 5½" stub (30 sx).
4. Spot 100' plug at base of 8 5/8" csg @ 1130-1230' (30 sx).
5. Place 20' cmt plug at surface (6 sx).
6. Place marker & clean up location.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Verbal approval received from Jim Sims 10-5-78.

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE District Production Mgr.

DATE 10-5-78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AS AMENDED

OCT 10 1978

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side