· · · · · · · · · · · · · · · · · · ·	Drm C-103	
60, OF COPICS DICCIVED	Supersedes O	
DISTRIBUTION NEW MEXICO OIL CONSERVATION COMMISSION	C+10 2 and C+1 Effective 1-1-1	
	· · ·	· ·
	So. Indicute Type	of Leuso
AND OFFICE	State X	Fre [
PERATOR	S. SILLE OF & Gu	a Lease No.
	L-6940	VIII I I I I I I I I I I I I I I I I I
SUNDRY NOTICES AND REPORTS ON WELLS too not use this form for hormals to male on to delaw on plug pack to a different reservoir.	<u>AIIIIIII</u>	<u>UUUUUUUU</u>
OIL X CAS OTHER-	7. Unit Agreemen	t lion.e
Name of Operator	8. Farm of Leave	Hame
Yates Petroleum Corporation	Reeves K	K State
Address of Operator	9. Well Ro.	
207 South 4th Street - Artesia, NM .88210	10. Field and Po	A second second
Location of Well		
UNIT LETTER D . 660 FEET FROM THE NOT th LINE AND 660 FEET FROM	Reeves P	nn
		HHHHHH
THE West LINE, SECTION 14 TOWNSHIP 185 RANGE 35E NMPM.	·/////////	HHHHHH
NYTYTYTYTYTYTYTYTYTYTYTYTYTYTYTYTYTYTYT	12. County	THINK .
//////////////////////////////////////	Lea	
NOTICE OF INTENTION TO: ERFORM BEMEDIAL WORK SUBSEQUEN EMPORARILY ABANDON ULL OR ALTER CASING CHARCE PLANS CASIN: TEST AND CEMENT JOB OTHER Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103. TD 11500'; PBTD 11460'. Cleaned out cement in hole. WIH W	Treat restinuted date of	ING CASING
Gun on 2-7/8" tubing and perforated 11282-11316' w/120 .50" Pulled guns and all had fired. WIH w/Guiberson Uni VI packe set packer at 11257' and treated perforations 11282-11316' MS acid and nitrogen. Swabbed & had a small show of gas an <u>TD 11500'; PETD 11235'.</u> COH w/tubing and packer. WIH and dumped 35' of cement on top of plug. WOC. WIH w/Tubing Conv Uni VI packer on 2-7/8" tubing, set packer at 10958' and pe w/32 .50" holes. GTS in 7 minutes. TSTM. <u>TD 11500'; PETD 10940'.</u> WIH w/CIBP on wireline set at 1097 cement on top of plug. WOC. WIH w/Tubing Conveyed Gun, Guib on 2-7/8" tubing, set packer at 10875'. Perforated 10900-1 holes (4spf). Dropped bar and had a slight blow. Swabbed COH. WIH w/Baker Lok-Set packer on 2-7/8" tubing set packe perforations 10900-10932'w/3000 gallons 15% DS-30 acid and Swabbed w/show of oil & water. Swabbed dry in 3 runs. COH TD 11500'; PETD 10715' WIH and set CIBP at 10750', dumped 3 of plug. WOC. POOH. WIH w/Tubing Conveyed Cun and perfor % Thereby certify that the information observe it tug and complete to the best of my knowledge and bellef. (conti	r on 2-7/8 w/4000 gal d oil. set CIBP a eyed Gun, rforated 1 5'. Dumped erson Uni 0932' w/12 and had no r at 10842 CO-2 w/bal 5' of ceme ated 9940-	" tubing, lons 7 ¹ 2% t ll270', Guiberson 0984-10992' 35' of VI packer .32" shows. '. Treated 1 sealers. nt on top 9980'
ichto in a di ad by		0.0 1079
Orig. Signed by Jerry Sexton	BATE SEP	26 131 -
Predvrb or		1