

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
L-2493	
7. Unit Agreement Name	
8. Farm or Lease Name	
Lea "30" State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Airstrip Bone Springs	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
GULF OIL CORPORATION

3. Address of Operator
P. O. Box 670, Hobbs, NM 88240

4. Location of Well
UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 30 TOWNSHIP 18S RANGE 35E NEARBY

15. Elevation (Show whether DF, RT, GR, etc.)

3946' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH w/tbg. Recovered sucker rods and pump. Set CIBP @ 8765'. GIH w/tbg to 8765'. Circulate hole w/300 bbls abandonment mud; cap CIBP w/35' cmt. POH w/tbg. Cut csg @ 7275' w/5½" csg cutter, csg free @ 7275'; pull 7275' 5½" csg. Ran 2-7/8" tbg to 7325'. Load hole w/abandonment mud. Spot 40 sx cmt plug 7325'-7225'. GIH w/2-7/8" tbg and top of cmt plug @ 7225' (bottom of tbg now @ 5930'). Spot 40 sx cement 5930' up to 5830'. POH w/2-7/8" tbg (bottom now @ 5155'). Spot 100' (40 sx) cement plug 5155' up to 5055'. POH w/tbg (bottom now @ 4050'). Spot 100' (40 sx) cement plug 4050' up to 3925'. POH w/tbg, GIH w/2-7/8" tbg. Tagged top of plug @ 3920'. Spot 100' (40 sx) cement plug 1964' up to 1864'. POH w/rest of tbg. Set 10 sx for surface plug, install dry hole marker, clean and clean location. P&A complete 5-20-80.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N.B. Sikes, Jr. TITLE Area Engineer DATE 5-22-80

APPROVED BY G.H. Statterman TITLE Oil & Gas DATE 5-22-80

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 23 1980

OIL CONSERVATION DIV.