DISTRIBUTION				Form C-103 Supersedes Old
SANTA FE	NEW ME	XICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE				
U.S.G.S.			•	State X Fee
LAND OFFICE				5, State Oil 6 Gas Lease No.
SPERATOR				L-2493
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.				
OIL X SAS	OTHER.			7, Unit Agreement Name
Change of Cylerator			8. Form or Lease Name	
GULF OIL CORPORATION  Address of Cperator			Lea "30" State	
	Habba NM	99910		1
P. O. Box 670	Hobbs, NM	88240		10. Field and Pool, or Wildcat
E	1980	North	LINE AND 660 FEET	Undes. Airstrip-Wolfcar
UNIT LETTER	7227 71000		The same of the sa	
THE West LINE, SE	CTION 30 TO	OWNSHIP 18-	-S RANGE 35-E.	MILLIAN MEN
mmm	TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	ian (Show wheeher	DF, RT, GR, etc.)	12. County
			Dr, Rr, OR, eac.	Lea
		945.7 GL	ature of Notice, Report of	
	FINTENTION TO:	To malcate N		JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG	AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPOPARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ASANDONMENT
PULL OR ALTER CASING	CHANG	E PLANS	CASING TEST AND CEMENT JOB $oxed{\Lambda}$	,
		,	OTHER	
		1 1		
OTHER		U		
Describe Frogosed or Completed work) SEE RULE 1103.	d Operations (Clearly stat	e al! pertinent dete	ails, and give pertinent dates, incl	uding estimated date of starting any proposed
M-G-F Rig #10 Spud 15" hole @ 1	10:30 am 2-18-79 1 csg (289'). S n complete @ 5:4	. TD @ 300' Set @ 300'. 5 pm 2-18-7	@ 2:30 pm 2-18-79. Cmt w/350 sx lite & '9. Cement circulated	Ran 6 jts & 1 cut jt 11-3/4 100 sx class "C" w/ <i>2%</i>
M-G-F Rig #10 Spud 15" hole @ 1 42# H-40 ST&C 8rd CaCl2. Plug down casing to 1000 ps	lO:30 am 2-18-79 d csg (289'). S n complete @ 5:4 si for 30 minute	et @ 300'. 5 pm 2-18-7 s - held o	@ 2:30 pm 2-18-79. Cmt w/350 sx lite & 79. Cement circulated	Ran 6 jts & 1 cut jt 11-3/4' 100 sx class "C" w/2%
M-G-F Rig #10 Spud 15" hole @ 1 42# H-40 ST&C 8rd CaCl2. Plug down casing to 1000 ps	LO:30 am 2-18-79  I csg (289'). S  In complete @ 5:4  si for 30 minute  Attornation above is true and cor	et @ 300'. 5 pm 2-18-7 s - held o	@ 2:30 pm 2-18-79. Cmt w/350 sx lite & 79. Cement circulated	Ran 6 jts & 1 cut jt 11-3/4' 100 sx class "C" w/2%
M-G-F Rig #10 Spud 15" hole @ 1 42# H-40 ST&C 8rd CaCl2. Plug down casing to 1000 ps	LO:30 am 2-18-79  I csg (289'). S  In complete @ 5:4  si for 30 minute  Attornation above is true and cor	et @ 300'. 5 pm 2-18-7 es - held of	@ 2:30 pm 2-18-79. Cmt w/350 sx lite & 79. Cement circulated	• WOC 18 hours. Tested
Describe Frogosed or Completes work) SEE RULE 1103.  M-G-F Rig #10 Spud 15" hole @ 1 42# H-40 ST&C 8rd CaCl2. Plug down casing to 1000 ps	LO:30 am 2-18-79  I csg (289'). S  In complete @ 5:4  si for 30 minute  Attornation above is true and cor	et @ 300'. 5 pm 2-18-7 es - held of	@ 2:30 pm 2-18-79. Cmt w/350 sx lite & 29. Cement circulated to	Ran 6 jts & 1 cut jt 11-3/4 100 sx class "C" w/2% • WOC 18 hours• Tested