

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-101  
Revised 10-1-77

5a. Indicate Type of Lease  
State ☒ ☐ ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Re-entry  
2. Name of Operator  
Steve Sell  
3. Address of Operator  
P. O. Box 5061, Midland, Texas 79704  
4. Location of Well  
UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM  
THE East LINE, SECTION 30 TOWNSHIP 18S RANGE 35E N.M.P.M.

7. Unit Agreement Name  
8. Farm or Lease Name  
Lea "SE" State  
9. Well No.  
#1  
10. Field and Pool, or Without  
Airstrip

15. Elevation (Show whether DF, RT, GR, etc.)  
3947' GRD

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                           |                                                      |                                                      |
|------------------------------------------------|-------------------------------------------|------------------------------------------------------|------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>             |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDON <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |                                                      |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-24-87 Pull rods and tubing.  
Set CIBP at 4600' and dump 35 sx. of cement on top of plug.
- 3-25-87 Circulate hole with 9.5# brine with 25# per bbls. of salt gell.  
Spot 25 sx. plug from 3615-3415'.  
Cut 5½" casing at 3015' and pull.  
Spot 35 sx. plug from 3084'.
- 3-26-87 Tag top of plug at 2954'.  
Spot plug from 1111-980'.  
Spot 10 sx. surface plug and install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Williams TITLE Agent DATE 3-26-87  
APPROVED BY R A Rader OIL & GAS INSPECTOR DATE 300 12 1988