

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Amoco Production Company

Address of Operator

P. O. Box 68 Hobbs, NM 88240

Location of Well

UNIT LETTER E 1990 FEET FROM THE North LINE AND 511 FEET FROM

THE West LINE, SECTION 34 TOWNSHIP 18-S RANGE 38 33-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3647' DF

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to increase productivity by the following method:

Pull rods and pump. Run Base Gamma Ray Temperature survey. Run tubing, packer, and tailpipe and tailpipe set at 6890'. Spot 250 gallons 15% NEFE HCL acid. Acidize with 4000 gallons 15% retarded HCL acid. Flush with 2% KCL water. Swab load and evaluate productivity.

0+4-NMOCD, H 1-Hou 1-Susp 1-GPM

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Greg Mitchell

TITLE Admin. Analyst

DATE 6-30-81

Orig. Signed by

Jerry Sexton

APPROVED BY Don L. Supt.

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: