

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
MAIL		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease

State ☐For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION 250 OF PART 1 (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Turner Tr. 2
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 30
4. Location of Well UNIT LETTER <u>E</u> <u>1990</u> FEET FROM THE <u>North</u> LINE AND <u>511</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Whedcat Und. Hobbs Drinkard
11. Elevation (Show whether DF, RT, GR, etc.) 3635 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
 CHANGE PLANS ☐

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOBS ☒

ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐

OTHER ☐OTHER Set cmt plug and sidetrack hole ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran a cement plug from 4259'-3859'. Cemented with 355 SX Class H cement with 1/4 of 1% CFR-2 and 2% CACL. Plug down 11:45 a.m. 9-12-79. WOC 22 hrs. Drilled cement from 3816'-3847'. Kicked off at 3847' to side track junk in hole. Drilled to 4077'. On trip out of hole drill pipe stuck at 2264'. Backed off at 2234'. Bit at 2844'. Ran overshot and worked fish from 2234' to 2225' and overshot came off fish. Fish fell, and split into two sections. Reamed key seat from 2121'-2307'. Ran overshot and tagged first section of fish at 3575'. Pull out of hole and hit tight spot 2416'-2350'. Reamed hole from 2107'-2418'. Screwed into fish at 3579'. Jarred on fish, but would not come. Ran string shot and backed off at 3826'. Recovered 1 joint drill pipe and 7 drill collars. Jar on fish. Ran string shot and back off at 3913'. Recovered 3 drill collars. Catch second section of fish at 3850'. Backed off

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kay Grix TITLE Administrative SupervisorDATE 10-10-79

(CONTINUED)

APPROVED BY

Orig. Signed By

Jerry Sexton

TITLE

DATE

OCT 12 1979

CONDITIONS OF APPROVAL, IF ANY

Dist 1, Supv

0+4-NMOCD,H 1-Hou 1-Susp 1-BD

at 3910'. Recovered 2 drill collars. Ran string shot and backed off second section at 3940'. Recovered 1 drill collar. Screwed into first section and backed off at 3941'. Recovered 1 drill collar. Could not screw into first section at 3941. Attempted to drill by fish. No progress past 3944'. Ran jet cutter and cut second section at 3969'. Did not part. Ran jet cutter and cut at 3961. Did not part. Unable to recover fish. Fish #1 consists of 1 - 6-1/2" drill collar. Fish #2 consists of 1 - 12-1/4" bit, 1 - bottom hole reamer, 3 - 8" drill collars and 1 - 6-1/2" drill collar. Propose to set a 400', 355 SX Class H cement plug from 3940'-3540' and kick off to side track junk in hole.

RECEIVED

OCT 11 1962

O.C.D. HOBBS, OFFICE