

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
ALBUQ.		
EL PASO		
UTAH		
NEW MEX.		
OTHER OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUMMARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DOWN TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name	
2. Name of Operator Amoco Production Company		8. Farm or Lease Name Turner Tr. 2	
3. Address of Operator P. O. Box 68, Hobbs, NM 88240		9. Well No. 30	
4. Location of Well UNIT LETTER E 1990 North 511 WEST 34 18-S 38-E LINE, SECTION TOWNSHIP RANGE NMPM.		10. Field and Pool, or Without Und. Hobbs Drinkard	
11. Elevation (Show whether DF, RT, GR, etc.) 3635 FL		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Set Cmt plug and sidetrack hole	CASING TEST AND CEMENT JOB ☐	OTHER ☒ Fishing bit X drillpipe

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to a TD of 4886'. Ran deviation survey and Eastman tool stuck in shock sub on top of bit. Unable to recover survey tool. Bit plugged off. Start out of hole and stuck drill pipe with bit at 4856'. Attempted to perforate drill collar at 4237' to establish circulation. Could not perforate drill collar. Ran free point. Drill pipe stuck at 4205'. Backed off drill pipe at 4171'. Started in with washpipe and reamer. Hit a tight spot at 1200' and reamed to 1775'. Wash over fish from 4171'-4295'. Screwed into fish and backed off and recovered one joint drill pipe and one drill collar. Top of fish 4271'. Wash over from 4271'-4292' and recovered cross over sub and sliced drill collar. Top of fish at 4277'. Top of fish is a drill collar sliced in half lengthwise. Unable to recover fish. Propose to spot a 400', 355 SX Class H cement plug from 4277'-3877' and kick off at approx. 3970' to

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(CONT)

SIGNED Ray Cox TITLE Administrative Supervisor DATE 10-10-79

Orig. Signed by Jerry Sexton DATE OCT 12 1979

APPROVED BY Dist. 1. Supv. TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

0+4-NMOCD, H 1-Hou 1-Susp 1-BD