Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

I.M. (	Dh	Jons.	Division	r.
		1		EC

P.O. Box 1980 Hobbs, NM 8824 FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

NM	4312	

DOKENO OF ZEED INTERPOLATION		NM 4312	
SUNDRY NOTICES  Do not use this form for proposals to dri  Use "APPLICATION FOR	6. If Indian, Allottee or Tribe Name		
SUBMIT	7. If Unit or CA, Agreement Designation		
I. Type of Well Oil Well Well Other	8. Well Name and No.		
2. Name of Operator Nearburg Producing Company	Pennzoil Federal #1  9. API Well No.		
3. Address and Telephone No. P. O. Box 823085, Dallas, Texas 75382-3085 (214) 739-1778 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2180' FSL & 660' FEL, Sec. 1, 19S, 33E		10. Field and Pool, or Exploratory Area  North Quail Ridge-Morrov  11. County or Parish, State  Lea Co., New Mexico	
12. CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA	
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment    Abandonment	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
PROPOSED STARTING DATE  1) MIRU workover unit. NU  2) POOH w/Morrow completion  3) RIH w/cement bond log an	equipment d determine top of cement (+9,450'). of cement. Spot 35' cement on top of		

14. I hereby ceptify that the Torrect order of true and correct  Signed	January 13, 1997
(This space for Federal or Suite office use)  (ORIG. SGD.) DAVID R. GLASS  Title PETROLEUM ENGINEER	JAN 15 1997
*When well is permanentely plugged, the CIBY DERW THE BENE	Springs Access to W
Title. 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States or representations as to any matter within its jurisdiction.	any false, fictitious or fraudulent statements

6) Perforate 2nd Bone Spring carbonate from 9,300' - 9,378' w/2 JSPF.

7) Stimulate as necessary. Place well on production.

ND BOPE. RDMO workover unit.

8)

9)