Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

ate of New Mexico Energy, Minerals and Natural Resources Department

Form C	-103
Revised	1-1-89

DISTRICT Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 87504-20	DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO. 30-025-26587			
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: WELL WALL OTHER THE BEST OF WELL OTHER SURE PERMITS OTHER A WELL No. 1. Type of Well: WELL WALL OTHER Bleddoo Petro Corp 1. Address of Operator 3908 N. Peniel, Suite 500, Bethany, OK 73008 4. Well Lossidoe Use Liter E 1980 Feet From The North Lise and 660 Feet From The West Lea Socion 9 Township 18S Range 35E NMFM Lea Costay 10. Diseration (Show whether DF, REB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ASANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ASANDON CASING TEST AND CEMENT JOB DITEMPORABILY ABANDON CHANGE PLANS XI CASING TEST AND CEMENT JOB Previously submitted form C-103 to plug and abandon (5/1/1991) Prepose to: 1. Swage out partially collapsed casing. 2. Set cast from bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 1. Test for production.				5. Indicate Type of Lease			
CONDITUSE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUS APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well:		•	6. State Oil & Gas Lease No.				
Out Charge County Charge County Charge County County	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name				
Bledsoe Petro Corp 3 Addition of Openine 1, Suite 500, Bethany, OK 73008 4 Will Lossibe Unit Letter E : 1980 Foot From The north Lios and 660 Feet From The west I Section 9 Township 18S Range 35E NMTM Lea County Section 9 Township 18S Range 35E NMTM Lea County 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PEFFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORABILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datas, including estimated date of starting any proposed work) SEE RULE 1103. Previously submitted form C-103 to plug and abandon (5/1/1991) Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 1. Test for production. Thereby certify that the information above is too, and complete to the best of my knowledge and belief. TIME Petroleum Engineer DATE 12/14/93 THE Petroleum Engineer DATE 12/14/93 THE PETROLEUM SIGNED BY JERRY SEXTON	OH OMS	OTHER		Gulf S	tate		
3908 N.Peniel, Suite 500, Bethany, OK 73008 4. Well Location Unit Letter E: 1980 Feet From The	2. Name of Operator			8. Well No.	3		
Unit Letter E: 1980 Feet From The North Line and 660 Feet From The West L Socion 9 Township 188 Range 35E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: 12. Describe Proposed or Completed Operations (Charly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 13. Previously submitted form C=103 to plug and abandon (5/1/1991) Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. 1. Indicate Nature of Notice, Report, or Other Data County State Units and Subsequence of State Units (Notice) Plug and abandon (5/1/1991)	3908 N.Peniel,Suite	(Operator) i		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK		80 Feet From The north	Line and660	Feet From 7	The west	Line	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK	Section 9	IOMURID		NMPM L	ea	County	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Previously submitted form C-103 to plug and abandon (5/1/1991) Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Petroleum Engineer DATE 12/14/93 TITLE Petroleum Engineer DATE 12/14/93 TITLE OF FRINTINAME TOM CONTON JERRY SEXTON		10. Elevation (Show whether I	DF, RKB, RT, GR, etc.)	1			
TEMPORABILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:							
CASING TEST AND CEMENT JOB OTHER: OTHER:	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	i 🗌	
DTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Previously submitted form C-103 to plug and abandon (5/1/1991) Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKINATURE TITLE Petroleum Engineer DATE 12/14/93 TYPE OR PRINT NAME TOM CONTON (405) 789-5053 TELEPHONE NO.	TEMPORARILY ABANDON	CHANGE PLANS XX	COMMENCE DRILLING OPNS. DLUG AND ABANDONMENT				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Previously submitted form C-103 to plug and abandon (5/1/1991) Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKINATURE TIME FOR PRINT NAME Tom Conroy (405) 789-5053 TELEPHONE NO. (105) 789-5053 TELEPHONE NO.	PULL OR ALTER CASING		CASING TEST AND CEMENT JOB				
Previously submitted form C-103 to plug and abandon (5/1/1991) Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKINATURE TITLE Petroleum Engineer DATE 12/14/93 TYPEOR PRINT NAME TOM Conroy (405) 789-5053 TELEPHONE NO.	OTHER:		OTHER:				
Propose to: 1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE TOM CONTROL TITLE Petroleum Engineer DATE 12/14/93 TYPE OR PRINTINAME TOM CONTROL (405) 789-5053 TELEPHONE NO.		ations (Clearly state all pertinent details, an	d give pertinent dates, includ	ding estimated date of	starting any proposed	i	
1. Swage out partially collapsed casing. 2. Set cast iron bridge plug at 8500', spot 3 sx cement on plug. 3. Perforate Bone Springs 7060'-7085' and 6814'-6840' 4. Test for production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Tom Conroy TITLE Petroleum Engineer DATE 12/14/93 TYPE OR PRINTI NAME Tom Conroy (405) 789-5053 TELEPHONE MO.	Previousl y subm	nitted form C-103 to plu	ng and abandon (5/1/1991)			
SIGNATURE TOM CONTOY PRINT NAME TOM CONTOY (405) 789-5053 TELEPHONE NO. (This space for State Use)	 Swage out Set cast Perforate 	iron bridge plug at 850 e Bone Springs 7060'-70	0', spot 3 sx c	ement on plu 1840'	ıg.		
(This space for State Use) OBJECTIVAL SIGNED BY JERRY SEXTON	2000			ngineer	DATE12/1	4/93	
ONICINAL SIGNED BY JERRY SEATON	TYPE OR PRINT NAME TOM CONTO	у /	(405) 789-5	5053	TELEPHONE NO.		
DISTRICT I SUPERAISON	ORIGINA	CTRICT I SUPERVISOR	n e		DATE DEC 2	0 1993	