

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.N.	
LAND OFFICE	
OPERATOR	

WATER CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
L-786

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO STRENGTHEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Energy Reserves Group, Inc.	8. Farm or Lease Name Gulf State
3. Address of Operator P. O. Drawer 2437, Midland, Texas 79702	9. Well No. 3
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 18-S RANGE 35-E N.M.P.M.	10. Field and Pool, or Wildcat Buckeye Abo
11. Elevation (Show whether DF, RT, GR, etc.) 3944.5	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 2-16-82 TD 9200' PBDT 9151'. MIRU workover rig. Tie onto 4 1/2" & cut same w/wireline cutter @ 1890'. Pulled & laid down 47 jts 4 1/2" csg.
- 2-17-82 TIH w/5 1/4" swage, Bump sub, jars, 6-3 1/2" DC on 2 3/8" tbq. Swage from 1835' to 75' & came free. Change out swage to 5 3/4" & swage same interval. Change out swage to 6" swage 1835' to 50' & stopped. TOH
- 2-18-82 BHA-Bumper sub, oil jars, 12-3 1/2" DC & swage. TIH w/6" csg. Swage, swage 1847' to 1881'. TOH. TIH w/6 1/4" csg. Swage, swage 1847' to 1881'. TOH. TIH w/6 5/8" csg. Swage, swage 1847' to 1881'. TOH. TIH w/ 6 7/8" csg. Swage 1847' to 1881'. Tagged 4 1/2" csg stub.
- 2-19-82 Checked 8 5/8" csg 1847' to 1881' w/6 7/8" swage-had small amount drag. TOH w/swage. TIH w/ 6 3/8" OD flat bottom mill w/guide shoe. Mill 1 1/2' off 4 1/2" csg stub from 1890' to 1891.5' (W. L. Meas.) TOH w/mill TIH w/4 1/2" overshot, bumper sub, jars, 6-3 1/2" DC & 6 stands. 2 3/8" tbq tbq-SD.
- 2-20-82 Finished TIH w/4 1/2" overshot. Caught 4 1/2" fish. TIH w/string shot & back off 4 1/2" csg @ 2402'. TOH w/13 jts. 4 1/2" csg. TIH w/7 7/8" swage, 3 1/2" bumper sub, 3 1/2" jars, 12-3 1/2" DC. Swage 8 5/8" csg. 1847' to 1863.
- 2-21-82 Finished swaging out 8 5/8" csg from 1863' to 1881'. TIH to 2402' & tag 4 1/2" csg. TOH. TIH w/cmt. Bond log. Ran log 1500' to 2400'. Good cmt 1500' to 1804', no cmt

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Robertson R. L. Robertson TITLE Production Engineer II DATE 3/23/82

ORIGINAL SIGNED BY

JERRY SEXTON

APPROVED BY DISTRICT SUPER.

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 2 1982