

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

3a. Indicate Type of Lease

State ☒Fee ☐

3. State Oil & Gas Lease No.

X-3556

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER- <u>PXA</u>	7. Unit Agreement Name
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>	8. Firm or Lease Name <u>State 42</u>
3. Address of Operator <u>P.O. BOX 68, HOBBS, NEW MEXICO 88240</u>	9. Well No. <u>4</u>
4. Location of well UNIT LETTER <u>14</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat <u>(Strip) Bone Springs</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3965.3' GR</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
 CHANGE PLANS ☐

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐

OTHER ☐OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows: MDSU x pull rods x pump. Release tubing anchor x POH x tubing. RIH x cast iron bridge plug for 5 1/2" casing x set CIBP at 9100' x cap x 35' Class H Heat Cement. Above CIBP spot 31 bbls 10# brine water x 25# gel/bbl. Pull up to 7760' x spot a 25 sk Class H Heat Cement plug from 7760'-7560'. Spot 80 bbls 10# brine x 25# gel/bbl above plug at 7560'. Pull up to 4100' x spot a 25 sk Class H Heat Cement plug from 4100'-3950'. Spot 31 bbls 10# brine x 25# gel/bbl. (over)

O+5: NMOCD-HOBBS; 1-J.R.BARNETT HOU RM. 21.156; 1-E. J NASH HOU RM. 4.206; 1-BAO

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beverly A. Ottwell TITLE SR. ADMINISTRATIVE ANALYST DATE 4-22-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

PXA State #22 No. 4 Continued

above plug 4100'-3900'. Fall up to 2565' x spot a
25 at Class H Neat Cement plug from 2565' to 2365'.
Spot 47 barrels of 10# brine x 25# gel/tbl above
plug from 2565' to 2365'. POH x RIH x brine to 350'
x 4 55PF. Tie into 5 1/2" casing x Rotolok Circula-
tion x the 5 1/2" - 9 5/8" casing Annulus. Pump 170 at
Class H Neat Cement and circulate 5 1/2" casing. This
breakhead on Annulus and pressure remaining.
Cement, leaving cement to surface in 5 1/2" casing.
Cap well x install abandonment marker.

MOSU.

RECEIVED
APR 23 1986
NORRIS OFFICE