STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION NO. 07 COPIES SCCCIVED Form C-101 DISTRIBUTION P. O. BOX 2088 Revised 19-1-7 SANTA FE SANTA FE, NEW MEXICO 87501 FILE Sa. Indicate Type of Lease U.S.G.S. State Foo LAND OFFICE 5. State Oil & Gas Lease No. OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS 5 FORM FOR PROPOSALS TO PRILL OF TO SEPPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -- " (FORM C-101) FOR SUCH PROPOSALS.) WELL X . Name of Operator 8 Farm of Lease Name State HO Amoco Production Company 9. Well No. . Address of Operator P. O. Box 68 Hobbs, NM 88240 10 Flori and Col or Wildcat Location of Well Upper Bone Springs 1780 FEET FROM THE _ South 26 18-S 34-E East 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3975' GR Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ORM REMEDIAL WORK COMMENCE DRILLING OPHS. PLUG AND ARANDONMEN GRARILY ABANDON CASING TEST AND CEMENT JOB ULL OR ALTER CASING Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to increase production by the following method: Run tubing and treating packer and set packer at 9100' with 3 joints of tailpipe. Acidize well with 3500 gallons of 15% NE-FE acid in 3 stages and separated with 200# of mothballs carried in 400 gallons of gelled brine after first two stages. Swab well. Install pumping equipment and return to production. -1-GPM 0+4-NMOCD, H 1-Hou 1-Susp crify that the information above is true and complete to the best of my knowledge and belief. if. I hereby

Assist. Admin. Analyst

CONDITIONS OF THE POVALL IF ANY

3-20-81