

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-4883	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
Name of Operator Amoco Production Company		8. Form or Lease Name State HR
Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Well No. 2
Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Airstrip Wolfcamp
15. Elevation (Show whether DF, KT, GR, etc.) 3954.9		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> FULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <u>Fishing</u> <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
---	---	--	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to a TD of 1613' and stuck drill pipe. Backed off drill collar at 1495'. Could not jar fish loose and was unable to regain circulation. Left bit, 2 drill collars, reamer, and 1 drill collar in the hole. Propose to plug and abandon per the following procedure:

- Spot a 100' plug over top of fish at 1495'.
- Spot a 200' plug across bottom of red bed. WOC and tag plug.
- Spot a 100' plug in/out of 13 3/8" casing shoe at 302'.
- Spot a 20 sx surface plug.
- Will skid rig 50' South and spud State HR #2Y.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis TITLE Admin. Analyst DATE 5-1-80

Orig. Signed by
Jerry Sexton

APPROVED BY Dick L. Supp. TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

0 + 4 NMOC-D-H 1-Hou 1-Susp 1-LRF 1-Mesa 1-Prop 1-South of D14 1-Prop

RECEIVED

MAY 1 1980

OIL CONSERVATION DIV.