

N. M. OIL CONS. COMMISS
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

approved.
et Bureau No. 42-R1424.
GNATION AND SERIAL NO.

NM 21171

6. IF INDI ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL & 1980' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Com "4" Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Bone Springs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 4-T19S-R32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3660' GL

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

POH with packer and tubing. Set CIBP at 8500', test 500#; cap with 35' cement. Load hole with mud. Cut casing off 10' above free point. Pull casing. Circulate hole with abandonment mud. Spot 50' cement inside cut off casing and 50' above. Spot 100' cement plug 5500'-5400'. Spot 100' cement plug 4225'-4125'. Spot 10 sack surface plug. Erect dry hole marker. Clean and clear location.

RECEIVED
FEB 12 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED R.D. Pitre TITLE Area Engineer

(This space for Federal or State office use)

APPROVED BY SEE ATTACHED FOR TITLE CONDITIONS OF APPROVAL

CONDITIONS OF APPROVAL

*See Instructions on Reverse Side

APPROVED

DATE

FEB 17 1982

JAMES A. GILLHAM
DISTRICT SUPERVISOR