ENERGY AND MINERALS DEPARTMENT

wa. or Cortes Secrives	T	
DISTRIBUTION	1	
BANTA FE		
FILE	1	1
U.S.G.S.	1	
LAHO OFFICE		1

JL CONSERVATION DIVISIO

DISTRICT I SUPERVISOR	1 1 2	DATE IN IN TOUR
ORIGINAL SIGNED BY JERRY SEXTON		"FEB 2 2 198 3
*ICHEO (Karley M. Herring TITLEA	ssist. Admin. Analyst	DATE 2-17-83
1d. I hereby cerally that the information above is true and complete to the b	ost of my knowledge and beisef.	
	1-CMH	ntly evaluating addition work.
well on 25/64" choke. Tubing pressure flo	w decreased to 200 psi in 9	min. Set choke on
unit and moved inswab unit 2-4-83. Swabbe new water. Moved out swab unit 2-9-83.		
tubing to 5000 psi above slips-OK. Pressu	re tested casing 600 psi-OK	. Moved out service
Killed well with 60 bbls brine and 2% KCL. Released packer and pulled tubing. Ran 2-3/8" tailpipe and packer. Tailpipe landed at 12,635' and packer set at 12,541'. Pressure tested		
blow on tubing. Recovered 55 BLW with a 3' flare. Swabbed 3 days and recovered 355 BLW and had 3' flare between runs. Moved out service unit 2-2-83. Moved in service unit 2-3-83.		
Moved out service unit 1-29-83. Moved in service unit 1-30-83. Ran swab and had light		
BOP. Release packer and pull tubing. Ran l jt. tailpipe with 1.78" profile nipple, 2 jts. tailpipe, packer, and 2-3/8" tubing. Packer set at 12,541'. REmoved BOP and installed tree.		
O in 2 hrs. Continued to flow. Recovered 130 BLW. Kill well and remove tree and install		
Pump 22,000 gals gell 2% KCL fresh water, 11,000 gal CO2 and 28,000# 20/40 mesh sand. Flush to perfs with 81 bbl 2% KCL brine water. Start flowing well on full open choke. Bled to		
at 12,520. Installed 10,000# tree and test tree to 9500 psi. Filled backside with 9 bbl 2% KCL brine water and test to 1,000 psi-OK. Replace valve on tree and rig up tree saver.		
Moved in service unit 1-24-83. Installed BOP and pulled 2-3/8" tubing and packer. Ran in hole 2-7/8" tubing and packer. Pressure tested tubing in hole to 9,000 psi. Packer set		
work) see HOLE 1103.		
17. Describe Proposed or Completed Operations (Clearly state all pertinent	details and two persons down for I I'	notional day.
OTHER .	OTHER	<u> </u>
PULL OR ALTER CASING CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDOHMENT
PERFORM REMODIAL WORK	REMEDIAL WORK	ALTERING CASING
NOTICE OF INTENTION TO:		REPORT OF:
Check Appropriate Box To Indicate		
15. Elevation (Show whe	ther DF, RT, GR, etc.) 3690.2 GL	12. County Lea
THE East LINE, SECTION 32 TOWNSHIP 18-S MANGE 32-E NMPM		
		MINIMINION.
unit Letter J . 1980 FEET FROM THE South LINE AND 1980		10. Field and Pool, or Wildeat Und. Morrow
P. O. Box 68, Hobbs, New Mexico 88240		1
Amoco Production Company 3. Address of Operator		State HU
2. Name of Operator		8. Farm or Lease Name
1.	SUCH PROPOSALS.)	7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS 100 HOT USE THIS FORM FOR PROPOSALS TO ORICL OR TO DEEPEN OF PL USE "APPLICATION FOR PERMIT -" FORM C-1011 FOR	ON WELLS	
OPERATOR		S. State Oll & Gus Leaun No.
U.S.G.S.		State X Foo
PILZ	EW MEXICO 87501	Su. Insticate Type of Lease
	BOX 2088	Form C-103 Revised 10-1

Expires 2/22/84