

Jennings Fed. Comm.
Procedure, page two

BOP 1400, Max 3600, Min. 2600, AV 3000. FP 3600, 151P 1700. Ball action 3000-3600.
Go Blaw. Well did not flow. Swab 9 hrs. Rec 21 B0. 53 blaw. FL 0-2600.
Swab 2½ hrs end. Rec 9 B0 7 blaw. FL 1500-2600. Rise FB lower thru perfs POH LD 2-7/8 WS
FB per RIH w/ 12-3/8 pump set up.. RIH w/ 2 x 1½ x 12 pump & (66) rods.
24 hr. P, 177 B0, 0 BLW (x) NFL 1 mcf gor 5.64 GR 27.3 60⁰ 79 Blaw.

RECEIVED

FEB 24 1987

HOBBY