

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCD-HOBBS

1-PS-ENGR

1-FILE

1-FOREMAN-ED FOWLER

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. E-7653
7. Unit Agreement Number
6. Form of Lease Name State AP
9. Well No. 1
10. Field and Pool, or Wildcat Vacuum Abo <i>Ref</i>
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR NOTICES TO DRILL OR TO ABANDON CAVING BACK TO A DIFFERENT RESERVOIR.
USE NOTICES FOR REPORT ON PRODUCTION, FOR OTHER OPERATIONS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator
Getty Oil Company

3. Address of Operator
P. O. Box 730, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM
West 9 18-S 35-E
THE LINE, SECTION TOWNSHIP RANGE NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3940.5 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Clean plugged perfs	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit.
2. Install BOP.
3. Pull rods and tubing.
4. RIH with tubing and packer.
5. Pump 300 gallons of 2% KCl water with soap and balls.
6. Swab load back.
7. Run rods and pump.
8. Place back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE February 26, 1981

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: