

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API #30-025-26834

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ INJECTOR		7. Unit Agreement Name
Name of Operator		N. HOBBS (G/SA) UNIT
Address of Operator		8. Form or Lease Name
SHELL WESTERN E&P INC.		SECTION 33
Location of Well		9. Well No.
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		232
UNIT LETTER <u>K</u> <u>1595</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1370</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18S</u> RANGE <u>38E</u>		10. Field and Pool, or Whichever
		HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
3636.19' GR		LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER <u>SQZD, PERF'D, ACD & RESQZD</u>	☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.)

7-25-86: Pulled injection equipment. Released pkr @ 3969' & POH. CO to 4308'.

7-28-86: Set CIBP @ 4120' & cmt ret @ 3935'. Sqzd San Andres perfs 4050' - 4101' w/100 sx Cls "C" cmt + 2% CaCl₂ + .2% Halad-4 followed by 50 sx Cls "C" cmt + 2% CaCl₂. WOC 24+ hrs.

7-29-86: Tagged TOC @ 3922'.

7-30-86: DO cmt (& cmt ret @ 3935') to 4108'. Pres tstd sqzd perfs 4050' - 4101' to 1000# for 5 min, held OK.

7-31-86: DO CIBP @ 4120' & pushed remains to 4395'. Perf'd San Andres 4050' - 4054' (2 JSPF). Acd perfs 4050' - 4248' w/2000 gals 15% HCl + 400 gals xylene.

8-01-86: Pres tstd sqzd perfs 4096' - 4101' to 750#, did not hold. Set CIBP @ 4120' & cmt ret @ 3937'. Resqzd perfs 4050' - 4101' w/25 sx Cls "C" cmt + 2% CaCl₂ + .2% Halad-4 followed by 25 sx Cls "C" cmt + 2% CaCl₂. WOC 24+ hrs.

(CONTINUED ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

E. J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE OCTOBER 22, 1986
Eddie W. Seay Oil & Gas Inspector
 APPROVED BY DATE

- 8-04-86: Tagged TOC @ 3932'. DO hard cmt (& cmt ret @ 3937') to 3997'. DO stringers to 4054'. Pres tstd sqzd perfs 4050' - 4054' to 1000# for 5 min, held OK. DO stringers to 4101'. Pres tstd sqzd perfs 4096' - 4101' to 1000# for 5 min, held OK. DO CIBP @ 4120' & pushed remains to 4395'.
- 8-05-86: Installed injection equipment setting Guiberson Uni-Pkr @ 3980' w/9000# tension. Pres tstd csg to 500# for 15 min, held OK. Returned well to injection.

10-27-86
10-27-86
10-27-86