

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-26930

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-1502

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Water Injection

2. Name of Operator
Phillips Petroleum Company

7. Lease Name or Unit Agreement Name
East Vacuum Gb/SA Unit
Tract 0524

3. Address of Operator
4001 Penbrook Street, Odessa, Texas 79762

8. Well No.
006

9. Pool name or Wildcat
Vacuum Gb/SA

4. Well Location
Unit Letter C : 1225 Feet From The North Line and 2580 Feet From The West Line
Section 5 Township 18-S Range 35-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3970' RKB; 3957' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Cleaned out and acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-19-92: MIRU DDU. NU BOP. Unset pkr. COOH w/tbg. RDMO Baker. Trip sand pump. Tag @ +4420'.
5-20-92: PU GIH w/4-3/4" bit, 4- 3-1/2" drill collars, & 2-7/8" tbg. Tag @ 4484', clean out iron sulfide to 4774', circ clean.
5-21-92: COOH w/tbg. LD drill collars. Trip 4-3/4" bit & 5-1/2" scraper to 4373'. MIRU Charger to pump 4500 gal CHIC IV acid.
5-22-92: RU swab.
5-26-92: RD swab.
5-27-92: PU GIH w/5-1/2" Baker LocSet pkr w/CO2 elements, 2-7/8" TK70 IPC J-55 tbg w/modified collars & seal lube thread dope. Test tbg to 5000# while GIH.
5-28-92: Set pkr @ 4400'. Load and test csg/tbg annulus to 500# for 30 min - ok. Hook up and start water injection. RDMO.
6-01-92: Rate 1676 BWPB @ 275#.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Reg/Proration DATE 06-01-92
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915) 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 04 1992

CD HOBBS OFFICE