

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
6. State Oil & Gas Lease No.	

## SUNDY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEVELOP OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name N.HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name Section 30
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 232
4. Location of Well UNIT LETTER K 140C FEET FROM THE south LINE AND 1370 FEET FROM THE west LINE, SECTION 30 TOWNSHIP 18S RANGE 38E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3650.77' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-15-80-12-16-80: Ran 115 jts 5 1/2" 14# K55 ST&C csg @4555'. Cmt'd 1st stage w/250 sx Class C + 18% salt + 1/4#/sx flocele. Cmt'd 2nd stage w/850 sx HLC cmt + 1/4#/sx flocele + 5#salt/sx followed by 155 sx of thick set + 5# salt + 1/4#/sx flocele. Bumped plug + closed DV tool, Cmt did not circ, but only back 22# differential pressure reaching surface. Completion rig will drill DV tool + pressure test csg @ TD.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR-REGULATORY & PERMITTING

DATE

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE