STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

48. 67 CO-1EB ACCEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.3.G.5.	
LAND OFFICE	
CREATOR	

CONDITIONS OF APPROVAL, IF ANY

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 . Revised 10-1-78

SANTA FE, NEW MEXICO 87501	•
FILE	5a. Indicate Type of Lease
U.S.G.S.	State X Fee
LAND OFFICE	5. State Oil & Gas Lease No.
O' EARTON	
CHARDA MOTICISC AND DEPONTS ON WELL S	mmmmmm.
SUNDRY NOTICES AND REPORTS ON WELLS (OG NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
USE "APPLICATION FOR PERMIT "" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1. OIL 648 T	7. Ont Agreement Nume
WELL WELL OTHER- INJECTOR	N. HOBBS (G/SA) UNIT
2. Name of Operator	8. Farm or Lease Name
SHELL OIL COMPANY	SECTION 32
3. Address of Operator	9. Well No.
P. O. BOX 991, HOUSTON, TX 77001	323
4. Location of Well	10. Field and Pool, or Wildcat
G 1370 NORTH 1400	HOBBS (G/SA)
UNIT LETTER G TOTO FEET FROM THE TOTAL LINE AND THOU FEET FROM	umminimini
EACH 32 18_C 38_E	
THE EAST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E NMPI	~ (())
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	////////
3638.66' GR	LEA ///////
Check Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
NOTICE OF INTENTION TO: SUBSEQUEN	NT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	PLUG AND ABANDONMENT
	_
	<u></u>
OTHER	
OTHER COMPLETE AS AN SA II, IIIu, III1 INI. X	
PMX-109 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	ng estimated date of starting any proposed
work) SEE RULE 1103.	
1. Pull RBP @4290' and reset @4264'. Spot +5' of sand on top of RBE	2. Spot 300 gals 15%
HCl - NEA double inhibited acid.	
2. Perforate Zone II 4062' - 4072',	
Zone III 4105' - 4190', and,	
Zone III $_{ m L}$ 4194' - 4252' (61' - 122 holes).	
-	
3. Pull RBP. CO to 4353' (PBTD).	
4. Test pkrs in blank pipe. Set pkrs and acidize perfs w/6800 gals	15% HCl - NEA acid.
1. Tobe plan in brane paper boo plane term mercane [1222 m, 1111 gian	
5. Set pkr @ + 3974'. Take injectivity test and complete.	
5. bee pin (_ 55,1 . Table 11,5001.1.1.)	
•	•
•	
the state of the boundary and a second and the best of the board of th	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
A. J. FORE TITLE SUPERVISOR REG. PERMITTING	SEPTEMBER 3, 1981
Aller of A	
	CEE CONTRACTOR
,如 基内部 ***	DATE OL!
	· ·