## STATE OF NEW MEXICO JERGY AND MINERALS DEPARTMENT

H COPICE SCCCIVED	]	
אסו דעימוויי דצום		
SANTAFE		
FILE		
U.S.O.S.	1_1	
LAND OFFICE		
OPERATOR	1 1	1

DISTRIBUTION  P. O. BOX 2088  SANTA FE SANTA FE, NEW MEXICO 8  FILE  U.S. O.S.  LAND OFFICE  OPERATOR  SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUE BACK TO A DIFFER  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	Form C-103 Revised 10-1-78  5a. Indicate Type of Leise State X Foe   5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	Sa. Indicate Type of Lense
SUNDRY NOTICES AND REPORTS ON WELLS	State X Foe [
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS	
	mmmmm —
	ENT RESERVOIR.
	7. Unit Agreement Name
OTHER- Injector	N. Hobbs (G/SA) Unit
	8. Farm or Lease Name
me of Operator	Section 32
SHELL OIL COMPANY	9. Well No.
dress of Ciperator	323
P. O. BOX 991, Houston, TX. 77001	10. Field and Pool, or Wildcat
cation of Well	1 - 1 - 1
UNIT LETTER G 1370 FEET FROM THE NORTH LINE AND	1400 FEET FROM (NODES (G) SK)
THE East LINE, SECTION 32 TOWNSHIP 18S HANGE	38 E NMPM.
	777777777444444444
15. Elevation (Show whether DF, RT, GR, et	(c.) 12. County
3638.66' GR	Lea
Check Appropriate Box To Indicate Nature of No	tice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
ORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
COMMENCE DR	ILLING OPHS. PLUG AND ABANDONMENT
CASING TEST A	AND CEMENT JOB
OTHER _P	Perforate, stimulate, and test SA X
	ransition zone
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give p	

11-19-80: Perforated 4272 - 4332 and acidized w/3400 gals 15% HCL - NEA acid.

10. I hereby cert	' /		te to the best of my knowledge and belief.	
XICHED LAS	hi Lintes for	A. J. FORE	TITLE Supervisor - REG./Perm.	DATE 3/23/81
	Ω(1 × 5 ) a. 5 <b>9</b> a. a.			DATE
CONDITIONS O	F APPROVAL, IF ANY:	· · · · · · · · · · · · · · · · · · ·	TITLE	