STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. or comits accrives	
DISTRIBUTION	
BANTA FE	
FILE	
U.S.G.B.	
LAND OFFICE	
OPFEATOR	

OIL CONSERVATION DIVISION

	DISTRIBUT	DISTRIBUTION P. O. BOX 2088					Form C-103 · Revised 10-1-7
	SANTA FE, NEW MEXICO 87501						Ket13eg 10-1-7
	FILE						5a. Indicate Type of Lease
	U.S.G.B.						State X Fee
	LAND OFFICE		į				5. State Oil & Gas Lease No.
	OPERATOR	L_L	j	4DT # 20 0	25 2624		S. State Gr. & Sas Eccso Ho.
				API # 30-0	125-26834		, mmmmmmmm
		SUNDR	Y NOTICES A	ND REPORTS OF	N WELLS		
	(DO NOT USE T	HIS FORM FOR PRO USE "APPLICAT	POSALS TO DRILL ION FOR PERMIT -	OR TO DEEPEN OR PLUG ' (FORM C-101) FOR SI	CH PROPOSALS.)		
1.		_			•		7. Unit Agreement Name
	WELL	WELL	отнев- Т	NJECTOR			N. HOBBS (G/SA) UNIT
2. No	ame of Operator						8. Farm or Lease Name
	SHELL OIL	COMPANY					SECTION 33
SHELL OIL COMPANY 3. Address of Operator							9. Well No.
			N TY 7700	.1			222
1	ocation of Well	991, nous10	ON, TX 7700	1			10. Field and Pool, or Wildcat
1		_					
	UNIT LETTER	<u>F</u>	L520 , EET ,	NORTH	LINE AND 1470	FEET FROM	HOBBS (G/SA)
	WEST	LINE. SECTIO	33	TOWNSHIP 18-	S RANGE 38-E	NMPM.	
ĺ							
TT	m		15. El	evation (Show whethe	DF, RT, GR, etc.)		12. County
			<i> </i> 3	646.1' GR			LEA ()))))
16.	<i></i>	711111111	*****				***************************************
		Check A	Appropriate B	ox To Indicate	Nature of Notice, Repo	ort or Oth	er Data
	N	OTICE OF IN	TENTION TO	:	SUBS	SEQUENT	REPORT OF:
		•		_	:		
PERF	ORM REMEDIAL WO	RK	P	LUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEM	PORARILY ABANDON				COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT
	OR ALTER CASING	Ħ	c	HANGE PLANS	CASING TEST AND CEMENT JO	, ľī	
,,,,,					1		II, III-U, AND III-L X
				. \square	INJECTOR.		
	THER			L			
17. D	escribe Proposed	or Completed Op-	erations (Clearly	state all pertinent de	ails, and give pertinent dates	, including	estimated date of starting any proposed
	ork) SEE RULE						•
	6/8-9/81:	Spotted 25	Ω ~a1a 159	UC1 NEA coid	Domf14:5 1/2" o	aa 7ana	II - 4054' - 4062';
	0/0-9/01.						11 - 4054 - 4002 ,
		Zone 111-0) — 4096 —	4182'; Zone	III-L - 4174' - 42	/0.	
			_		_		
	6-11-81:						tween pkrs in blank
		pipe to 10	000 psi - h	eld OK. Ac i d	ized perfs 4054' -	42.76	w/9500 gals 15% HCl
		NEA acid.	•				
	6-12-81:	Set pkr @3	1964' w/12,	000 $\#$ tension.	Well Complete.		_
				•			
				i			
		•					
			•		•		
	•						
	ui.	Λ					
18. I h	perely certify that	the information a	bove true and	complete to the best	of my knowledge and belief.		
	人//	X	ton				
	(SQ) d/	De ma	/ <u></u>				
* 15 KED	Prof C	my	A. J. F	ORE TITLE SUP	ERVISOR_REG./PERMI	rT1NG	DATE HILY 10, 1981
						10.00	
					*** * *** F177"	**************************************	

Diet L. Supv.

BATE JUL 16 1981