

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 12568	
2. NAME OF OPERATOR PETROLEUM DEVELOPMENT CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 9720-B Candelaria, N.E., Albuquerque, N.M., 87112		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1,980' FNL, 1,980' FEL		8. FARM OR LEASE NAME Roberts McKay Federal	
14. PERMIT NO.		9. WELL NO. #1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,630' GL / 3,649' KB		10. FIELD AND POOL, OR WILDCAT Undes. Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T19S, R32E	
		12. COUNTY OR PARISH Lea	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Work completed on 12/8/82:

1. Set CIBP @ 10,652'. Dumped 40 sack plug.
2. Jet cut 4½" casing @ 5,050'. P.O.H.
3. Set 15 sack plug from 7,465' to 7,262'.
4. Set 15 sack plug from 5,890' to 5,685'.
5. Set 40 sack plug from 5,103' to 4,916'. Tagged plug.
6. Set 40 sack plug from 4,410' to 4,320'. Tagged plug.
7. Set 40 sack plug from 465' to 340'. Tagged plug.
8. Set 30 sack plug @ surface.
9. Installed dry hole marker on 12/8/82.

RECEIVED

JAN 31 1983

MINERALS DIVISION  
ROCKWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Jim C. Johnson, Jr.  
(This space for Federal or State office use)

TITLE Field Manager

DATE 1/28/83

APPROVED BY Don Wood  
CONDITIONS OF APPROVAL, IF ANY:

TITLE AREA MANAGER  
CARLSBAD RESOURCE AREA

DATE 3-15-85

RECEIVED

MAR 18 1985

U.S. CUSTOMS  
AND BORDER PROTECTION